

# Oil Field Environmental Incident Summary

**Incident:** 20170609165944

**Date/Time of Notice:** 06/09/2017 16:59

**Responsible Party:** LIBERTY RESOURCES MANAGEMENT COMPANY, LLC

**Well Operator:** LIBERTY RESOURCES MANAGEMENT COMPANY, LLC

**Well Name:** T. HAUSTVEIT E 156-95-25-36-3MBH

**Field Name:** BEAVER LODGE

**Well File #:** 33134

**Date Incident:** 6/9/2017

**Time Incident:** 04:40

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 156

**Rng:** 95

**Sec:** 25

**Qtr:**

**Location Description:** 83.3% (25 gallons) of spill within containment on the Well site. 16.7% (5 gallons) of spill outside of containment on landowners field

**Submitted By:** Paul Weddle

**Received By:**

**Contact Person:** Paul Weddle

1200 17TH STREET, SUITE 2200

DENVER, CO 80202

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** No

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	25	Gallons	20	Gallons		

Brine

Other

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

75'x50 feet in total, of which 83% was in containment

**Potential Environmental Impacts:**

None. Landowner has been notified and all parties agree there is no environmental impact.

**Action Taken or Planned:**

All flowback crews will review the incident and the proper operation of the flowback separator to reduce future risk of this happening again. Location equipment and surrounding impacted area are being cleaned up per landowner and Liberty discussions.

**Wastes Disposal Location:** recovered oil will be processed onsite or trucked off to a third party facility

**Agencies Involved:**

### **Updates**

---

**Date:** 6/12/2017    **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a tank overflow, was not contained according to the report. Further follow-up needed.

---

**Date:** 7/6/2017    **Status:** Inspection

**Author:** Schiermeister, Robin

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on site at 10:00 on 6-29-2017. The weather was warm and sunny. The release went off the pad north of the CTB. The area offsite has been mowed; however, the area onsite still has oily vegetation and staining. The area offsite has the coordinates N48.312853 W102.832920 and spans approximately 50 feet by 30 feet. Further follow-up is needed in the fall to check for proper vegetative regrowth.